

Inspection Report

Report No.

CW-20120319-CLS-001

PRODUCT DESCRIPTION



Client Name: Sultan Triveni General Trading & Contracting	
Product Name: POF centerfolded film	
Inspector: Richard Li	
Report approver:	
Inspection location:	SHENZHEN, GUANGDONG, CHINA
Inspection date:	19/Mar/2012
Your reference number: N/A	
P/O number: ST-044-2011	
Inspection type : Container loading supervision(CLS)	
Supplier: Hubei Guancheng Biodegradable Plastic Products Co. Ltd	
Vendor: Hubei Guancheng Biodegradable Plastic Products Co. Ltd	
Order quantity : 720Rolls	See attached table
Pcs ready for inspection:	100% ready
Reference sample available:	NO

Factory cooperation	Factory organization	Inspector's opinion on the factory
Average	Average	Average

Loading starting time	Loading completion time
16 :10	17 :40

IMPORTANT REMARKS / GENERAL DEFECTS

- For all of items, actually found the net weight and gross weight were described differently on each of shipping box, but we could not check it due to no suitable equipment provided. (Pls. Refer to remark photos)
- Actually found the cargo were placed on 15 pallets in total to loading, which did not conform to client's instruction as 30 pallets in total. However, the carrier claimed that the products could not load in container completely if according to client required as 30 rolls per pallet, but now it does by current stacking way. (Pls. refer to the below item 'Loading Videos' of page 14 ')

LOADING AND PACKING REQUIREMENTS

1. Loaded Quantity

Expected Result	Result	Actual Finding / Comments
Total nb of Container(s) loaded: 20" : / 40" : / 40" HC :	Subject to client's decision	20" HC
Total nb of Pallets loaded:	Pending due to remark	15 pallets
Total nb of Cartons loaded:	Conform	720 cartons
Numbering of cartons: (to)	Subject to client's decision	No carton number found.
TOTAL NUMBER OF PIECES READY :		100% ready and see below attached table
Truck plate numbers		粵 BG5730

The attached table:

Container No	Product description	CTN Q'TY	Q'TY (pcs)	SEAL NO.
HJCU2911605	1#250/500MMX1067MX19MU	90 ctns	90 pcs	HAN JIN CH8316169
	2#300/600MMX1067MX19MU	90 ctns	90 pcs	
	3#350/700MMX1067MX19MU	90ctns	90 pcs	
	4#400/800MMX1067MX19MU	60ctns	60 pcs	
	5#450/900MMX1067MX19MU	60ctns	60 pcs	
	6#300/600MMX800MX25MU	90ctns	90 pcs	
	7#350/700MMX800MX25MU	60ctns	60 pcs	
	8#400/800MMX800MX25MU	90ctns	90 pcs	
	9#450/900MMX800MX25MU	90ctns	90 pcs	
	10#500/1000MMX800MX25MU	30 ctns	30 pcs	

2. Shipping Marks

a. Carton Front Mark

Expected Result	Result	Actual Finding / Comments
	Subject to client's decision	Refer to product photos

b. Carton Side Mark

Expected Result	Result	Actual Finding / Comments
	Subject to client's decision	Refer to product photos

3. Loading Process	
Client's specific instructions for Loading Process :	
N/A	
EMPTY CONTAINER	
Requested Check	Actual Finding / Comments
Container general conditions : - water - rust holes - dust - grease - general cleanliness	- no water - no rust holes - clean - no grease
Container door numbers	HJCU2911605
Inside container numbers	
Outside container numbers	

1/4 FULL CONTAINER	
Requested Check	Actual Finding / Comments
Loading method : - By hand or machine - Pallets or individual carton	-By hand & machine - Individual carton & pallets
Loading by the top or the back of the truck?	Loading by the back
Describe how the cartons are piled up (collapse risks)	Refer to photo below
How many layers of cartons inside the container ?	5 layers
Did any cartons fell on the floor during loading?	No

1/2 FULL CONTAINER	
Requested Check	Actual Finding / Comments
Did any cartons fell on the floor during loading?	No


3/4 FULL CONTAINER	
Requested Check	Actual Finding / Comments
Did any cartons fell on the floor during loading?	No

FULL CONTAINER	
Requested Check	Actual Finding / Comments
Is the container completely full? If no, describe how carton are tied together.	Yes, there is. The detail for reason pls. refer to remark and loading photos.
Is there any space between the top of the last layer of cartons and the roof of the container ?	Yes, there is. The detail for reason pls. refer to remark and loading photos.
Container(s) seals number	HAN JIN CH8316169
Did any cartons fell on the floor during loading?	No

CONTAINER CLOSING

Requested Check	Actual Finding / Comments
Are seals temporary or definitive?	Definitive seals

Remark photos



For all of items, actually found the net weight and gross weight were described differently on each of shipping box, but we could not check it due to no suitable equipment provided



PRODUCT PHOTOS

Expected Result	Result	Actual Finding / Comments
	N/A	Please see picture

Pictures:

Item No.: 1#250/500MMX1067MX19MU



Order quantity: 90ctns






Item No.: 2#300/600MMX1067MX19MU

Order quantity: 90ctns




Item No.: 3# 350/700MMX1067MX19MU

Order quantity: 90ctns



Item No.: 4#400/800MMX1067MX19MU



Order quantity: 60 ctns







Item No.: 5#450/900MMX1067MX19MU

Order quantity: 60 ctns





Item No.: 6#300/600MMX800MX25MU

Order quantity: 90 ctns



Item No.: 7#350/700MMX800MX25MU



Order quantity: 60 ctns






Item No.: 8#400/800MMX800MX25MU

Order quantity: 90 ctns




Item No.: 9#450/900MMX800MX25MU

Order quantity: 90 ctns



Item No.: 10#500/1000MMX800MX25MU

Order quantity: 30 ctns





Loading Pictures:



Container



Container door number



Container outside



Seal



Empty container



1/4 Full container



1/2 Full container



3/4 Full container



Full container



Left door of the container



Closed container



Seal detail on container

c. Outer packing:

Sealing method (staples - adhesive - plastic band - metal band): adhesive

Expected Result	Result	Actual Finding / Comments
	Subject to client's decision	Refer to below pictures

Photos





Loading Videos



The products in the warehouse



Full container

Other Photos



End of the Report